

Переключатели движковые

Q-864 13,2мм x 4мм h = 2,0мм  ~0,3А; 50В 8Р	Q-9908 угловой 14мм x 7мм h = 9,0мм  ~0,3А; 50В 8Р+4Р (корп)	Q-9008 угловой 14,2мм x 15,4мм h = 8,5мм  ~0,3А; 50В 6Р	Q-9744 угловой 14,5мм x 8мм h = 3,0мм  ~0,3А; 50В 6Р
Q-1203 14,5мм x 8,5мм h = 6,0мм  ~0,3А; 50В 10Р+2Р (корп)	Q-1730 15,5мм x 7,5мм h = 4,0мм  ~0,3А; 125В 6С	Q-1731 15,5мм x 7,5мм h = 4,0мм  ~0,3А; 125В 6С	Q-1202 угловой 16мм x 7мм h = 8,5мм  ~0,3А; 50В 6Р+4Р (корп)
Q-9906 16мм x 11мм h = 5,0мм  ~0,3А; 125В 3С	Q-9741 угловой 17мм x 8мм  ~0,3А; 50В 6Р+2Р (корп)	Q-9742 17мм x 8мм h = 15мм  ~0,3А; 50В 6Р+4Р (корп)	Q-865 18,5мм x 8,5мм h = 8,5мм  ~0,3А; 50В 6Р+2Р (корп)
Q-9175 угловой 19,5мм x 8,5мм h = 9,0мм  ~0,3А; 50В 6Р+2Р (корп)	Q-9832 20,7мм x 11мм h = 6,5мм  ~0,3А; 125В 8Р+2Р (корп)	Q-203 22мм x 8мм h = 5,0мм  ~0,3А; 125В 4Р+2Р (корп)	Q-1059 22,5мм x 8,5мм h = 5,0мм  6С
Q-1455 23мм x 13,5мм h = 5,5мм  ~0,3А; 125В 12Р+2Р(земля)	Q-9905 24,6мм x 7мм h = 8,5мм  ~0,3А; 125В 5Р+2Р (корп)	Q-9176 25мм x 10мм h = 6,0мм  ~0,3А; 125В 6Р+4Р(земля)	Q-2517 28мм x 18мм h = 7,0мм  ~0,3А; 125В 3С
Q-2518 28мм x 18мм h = 6,5мм  6С	Q-1732 29мм x 10мм h = 8,0мм  ~0,3А; 125В 12С+4Р(земля)	Q-9740 31мм x 9,5мм h = 9,0мм  ~0,3А; 125В 16С	Q-9319 38мм x 10мм  18Р+4Р(корпус)
Q-1549 31мм x 23мм h = 5,0мм  выкл - (вкл) ~10А; 250В 4С винт	Q-2841 38мм x 33,5мм h = 7,0мм  ~4А; 250В 4Свинт	Q-1065 31мм x 23мм h = 5,0мм  ~10А; 250В 4С винт	Q-2842 39мм x 19,5мм h = 4,0мм  ~2А; 250В 6С винт